"Drilled Shafts for Bridge Foundation Stability Improvement Ohio 833 Bridge over the Ohio River" An Update

Meigs County, Ohio Mason County, West Virginia

By Stan Harris, P.E. and Eric Kistner, P.E. FMSM Engineers



Geohazards in Transportation Appalachian Region Technical Forum August 1-2, 2007

Agenda


- I. Introduction/Background
 - A. General
 - B. Initial Slope Movement
 - C. Remediation Scheme
 - D. Instrumentation Plan
- II. Instrumentation Results/Recent Slope Movement
- III. New Instrumentation on Existing Bridge
- IV. Lessons Learned
- V. Question/Answer



I. Introduction/Background



Project Location



Project Team

 Owner: ODOT/WVDOH
 Designer: URS Corporation
 Contractor: Mahan/National Joint Venture
 Geotechnical Consultant – FMSM




Existing Structure





Proposed Structure






Fuller

May

Project Timeline





Fuller

May

Current State of Construction






Stability Issues/Slope Movement/Reaction


New Main Street Embankment Short-Term Stability Concerns Controlled Rate-of-Fill - Slope Inclinometers - Piezometers Initial Detection of Movement Additional Instrumentation



Original Extents of Slope Movement

POMERO 17, A-Axis








Probable Causes of Slope Movement


 Weak slickensided clay shale (mudstone)
 Possible ancient movement
 Construction activity/embankment
 Rapid drawdown cycles of Ohio River




Slope Geology/Geometry








Plan View of Stabilization Shafts





Revised Roadway Plan






Instrumentation Plan

- Site Slope Inclinometers, Piezometers
- Existing Bridge Tiltmeters, Survey Targets
- Touch Down Pier Strain Gauges, In-Place and Manually Read Inclinometer
- Stabilization Shafts Tiltmeters, Strain Gauges, In-Place and Manually Read Inclinometers



Stabilization Shaft Instrumentation Plan





II. Recent Slope Movement/ Instrumentation Results



Recent Movement (Oct '06 - Feb '07)

Detection

- Instrumentation Activity (late October)
 Tension Cracks (early December)
 Water Main Break (early December)
 Causes
 - Construction Activity
 River Fluctuation



Tension Cracks – 12/11/06






Construction Activity – 11/30/06





Ohio River Fluctuations





Tied Back Retaining Wall





Fulle

Scott 8 May


Results of Instrumentation

Site

- 4 Years of Data
- Numerous Inclinometers Sheared Due to Slope Movement
- Existing Bridge
 - 3 Years of Data
 - Abutment Tilt Due to Recent Movement
- New Bridge Touch Down Pier
 - 3 Years of Data
 - Top Deflection Due to Lateral Loading
- Stabilization Shafts
 - -2 Years of Data
 - Northernmost Shaft Being Loaded




Current Extents of Slope Movement



Limits of Movement



Existing Bridge Tiltmeter Results






Fuller

May

Existing Bridge Tiltmeter Results

Land Pier Top Tiltmeters



Fuller Mossbarger Scott & May

Stabilization Shaft Strain Gage Results

SS9: Moment Diagram


EN

GIN


E

ERS

With Linear Regression




Stabilization Shaft 9 – IPI Plot





Touch Down Pier Strain Gage Results

DS-54: Bending Moment History



EN

GIN

EERS

III. New Instrumentation on Existing Bridge

-Jointmeters (3 Joints on Ohio Side) -Tiltmeters on Linkage Assemblies -Strain Gages on Truss **Members**





IV. Lessons Learned

- Difficulty with Instrumentation Durability in Construction/River Environment
- Sole-Source Instrumentation Consultants
- Communication Between Contractor and Engineer Key
- Better Results from Tiltmeters/Strain Gages than IPI's
- Look for Agreement Between Instruments
- Human Intervention with Instruments Necessary At Times
- Installation and Access Can Be Difficult



V. Questions/Answers

