


I-40 Fill Slide, Roane Co. Tennessee

BY: Lori McDowell, PE
TDOT, Geotechnical Engineering

Location



Fill Slide area


I-40 WBL

I-40 EBL

Browns Gap




UTM GRID AND 1968 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET



CONTOUR INTERVAL 20 FEET
DATUM IS MEAN SEA LEVEL

THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS

FOR SALE BY U.S. GEOLOGICAL SURVEY, WASHINGTON, D.C. 20242,
TENNESSEE DIVISION OF GEOLOGY, NASHVILLE, TENN. 37219.




QUADRANGLE LOCATION

ROAD CLASSIFICATION

- Heavy-duty Poor motor road
 - Medium-duty Wagon and jeep track
 - Light-duty Foot trail
 - Interstate Route ○ U. S. Route ○ State Route
- In developed areas, only through roads are classified (TVA 123-NW)

CARDIFF, TENN.
N3552.5-W8437.5/7.5

Geology



Geologic Layering


Colluvium / gravity deposited material

Sandstone

Shale interval (weak) – Pennington formation


Limestone – Newman Limestone






Chronology of Site

- Construction started in Mid May 1967
- Removal of “undesirable material” in August of 1967.
- Fill material for that section of roadway started in late August of 1967.
- In January of 1968 landslide movements were first noted and March 7, 1968 work was halted.



LEGEND

- LAW AUGER-CORE BORING (LOCATED BY SURVEY, SPRING 1969)
- STATE AUGER-CORE BORING (LOCATED BY SURVEY, FALL 1968)
- STATE "ROBBINS DRILL" BORING (LOCATED BY SURVEY, FALL 1968)
- INDICATOR BORING
- METER RECORDER PIT



LAW ENGINEERING TESTING COMPANY ATLANTA, GEORGIA	
STATE OF TENNESSEE DEPT. OF HIGHWAYS NASHVILLE, TENN.	

First attempts at Remediation

- Installation of drainage facility
 - (April 8, 1968) A ditch on the upper side of the EBL approximately 607 feet in length, 15-20 feet deep and 10-12 feet wide with a perforated 8-inch corrugated metal pipe inside the ditch, topped with crushed stone, and a 42 inch cross-drain.

R1


After which, construction continued but movement was still noted.

R2

- (June 1968) Drilled shafts 35-40 ft. deep and 3 ft. in diameter filled with crushed stone were placed at the toe of the fill for a length of 200 ft.

In August of 1968 the 42 inch pipe had failed and was removed.

- In October of 1968 Law Engineering Testing Co. was contracted to determine failure mechanism and present recommendations.
- I2** – Used aerial photographs and full stereoscopic examination
- I3** – Subsurface investigation - nine borings in which six slope inclinometers were installed within and also four sealed piezometers were installed. Ground water levels monitored for all.
- I4** – Seismic activity monitoring



AIRPORT RD

CENTERLINE OF EBL

Law Engineering Findings

- There was evidence of movement in the past before any construction was done.
- There was an old gulley that bisected the slide that formed the headwaters of Black Creek
- The whole area has a high water table
- Possibility of different layers of aquifers due to the fracturing of the rocks.
- There is more than one slide happening along the whole slide, but one failure surface was identified.

Law Engineering Findings

- The original slope originally had a factor of safety of around 1.0.
- The main cause for the movement of the slope is ground water.
 - High water table in the fill
 - Possibility of more than one aquifer due to geology layering
 - Possible sealing/”pinching” of seeps or springs under fill
 - Noted movement of slide increased after heavy rain or snow melting

Law Engineering Findings


- Three primary factors:
 - 1) Unstable structure of the Pennington shale
 - 2) The large unbalanced weight of the fill within the slide zone.
 - 3) Ground water pressure within the Pennington Formation.

Methods of Stabilizing Slope Recommended by Law Eng.

- 1) Remove all weak Pennington Shale
- 2) Reduce weight of fill and lower grade
- 3) Use of a Retaining Structure
 - a) Buttress
 - b) Line of Drilled Shafts
 - c) In the form of a retaining wall
- 4) Bridging area of Failure
- 5) Shifting roadway horizontal into hillside (cut).
- 6) Drainage - deep drainage and horizontal drains

- From July 1968 to February 1969, the average movement of the slide was noted to be between 0.3 ft. to 0.5 ft. along the slope and increased in speed from February to May 1969 to a 2'-3' lateral movement.
- In October of 1969 plans were started for Remediation – Minimal solution chosen which was lowering the grade of roadway and installing 44 horizontal drains.

R3



IMPERVIOUS COVER

REMOVE

FILL BEFORE REMOVAL

WATER IN FILL

RANGE IN GROUND WATER LEVELS
IN SLIDE ZONE.

NEW 24" CMP DRAIN

ELEV 1250

DRAIN TRENCH

DRAIN TRENCH

SELECT GRANULAR

PS

PS

PS

PS

H

MP

LIMESTONE

PLS

12" CMP

PLS

18" CMP

PS







Rock Buttriss

t
e

15

- Between March-April 1974, there was an installation of 7 Slope inclinometers at the toe of the embankment and an observation well in the median and about 4 more located along the slope.
- On August 19, 1974, the last portion of the East Bound Lane of I-40 through the state of Tennessee is open to public.



- Movement noted through the slope inclinometer readings for the year of 1974 had a max movement of 3" horizontally and 6"-8" vertically

- Between September 1975 to December 1975
R6 33 additional drains were installed at two pads
I6 in a fan pattern at the centers of each ravine.




FIGURE 4. HORIZONTAL DRAIN LAYOUT AT PAD A AND PAD B ; 2001+00-2018+00 SLIDE (SHADED AREA INDICATES LENGTH OF INSTALLED HORIZONTAL DRAINS)

SCALE : 1" = 100'

Horizontal Drain Outlet as of 5-19-2003



Horizontal Drain Outlet as of 6-9-09



Stream created by horizontal drains



Due to slowing in movement, from 1977 to 1994 the only requirements for the area was an overlay of asphalt when needed.

In 1994, the Geotechnical Engineering section was requested by Maintenance to review the slide area.

- In 1994 to 1995, more horizontal drains were installed along the toe of the fill and down slope of the two pads.
- In June of 2003, three additional slope inclinometers were installed and data has been collected since.
- Rate of movement was averaging 0.1 to 0.2 inches per year from 2003 through 2009. Between 2009 and 2010, the rate of movement had increased to 0.6 inches for the year

LEGEND

- BOREHOLE LAW (FEBRUARY-MARCH 1969)
 - BOREHOLE TDOT (JULY-AUGUST 1969)
 - BOREHOLE TDOT (MARCH 1989)
 - SLOPE INDICATOR BOREHOLE
 - PIEZOMETER
 - TEST PIT
 - WELL RECORDER
 - BOREHOLE TDOT (JULY 1972) (SEE REFERENCE 4)
 - BOREHOLE TDOT (MARCH-APRIL 1974) (SEE REFERENCE 5)
 - BOREHOLE TDOT (SEPTEMBER 1974-JANUARY 1975) (SEE REFERENCE 6)
 - BOREHOLE TDOT (JUNE 2003) (SEE REFERENCE 7)
-
- ATTITUDE OF BEDDING
 - LATERAL FAULT DISPLACEMENT
 - VERTICAL FAULT DISPLACEMENT
 - INFERRED CONTACT
 - CONCEALED CONTACT
-
- 5% SLOPED HORIZONTAL DRAIN
 - 10% SLOPED HORIZONTAL DRAIN

FROM LAW REPORT (1969)
(SEE REFERENCE 3)

FROM LAW REPORT (1969)
(SEE REFERENCE 3)


FROM TDOT (1972)
(SEE REFERENCE 2)

NOTES

1. TO BE READ IN CONJUNCTION WITH THE TDOT CONTRACT DOCUMENTS AND GOLDER ASSOCIATES INC. TECHNICAL SPECIFICATIONS FOR THE I-40 LANDSLIDE SPECIAL DRAINAGE MEASURES, DATED SEPTEMBER 2010.
2. LOCATIONS OF ALL BORINGS AND CONTACTS ARE APPROXIMATE, BASED ON OVERLAY OF SCANNED IMAGES AND LOCATIONS ACCORDING TO BOREHOLE LOGS, BOREHOLE LOG INFORMATION CONTAINED WITH THE TDOT "INFORMATION TO BIDDERS" DOCUMENTATION.
3. THE GEOLOGIC PLAN IS UNCHANGED FROM THE 1969 LAW REPORT (REFERENCE 3).
4. THE BORING DESIGNATIONS FOR THE 1972 AND LATER TDOT EXPLORATIONS FOLLOW: INSTRUMENTATION-YEAR OF EXPLORATION-ORIGINAL BOREHOLE NO., WITH I=INCLINOMETER, P=PIEZOMETER, W=WELL, AND B=BORING (NO INSTRUMENTATION). THE BORING DESIGNATIONS FOR EARLIER EXPLORATIONS FOLLOW LAW'S 1969 NOMENCLATURE.
5. LOCATION OF B-74-6A IS APPROXIMATE BASED ON AMBIGUOUS STATION AND OFFSET NOTED ON LOG, STA. 2010+00= 100 FT. EAST OF CENTERLINE DITCH.
6. NOT KNOWN IF FAN DRAINS AT PAD A AND PAD B ARE THE "AS PROPOSED" OR "AS-BUILT" LENGTHS UNDERSTOOD THAT MOST WERE INSTALLED BETWEEN 90-100 FT., RATHER THAN UP TO 800 FT., AS PROPOSED, SO ON THAT BASIS THE FAN ARRAYS SHOWN ON THIS DRAWING ARE MORE LIKELY THAN NOT TO BE "PROPOSED" RATHER THAN "AS-BUILT".


REFERENCES

1. BASE IMAGE IS AN ELECTRONIC SCAN, BASE MAP TOPOGRAPHY BY PHOTODIAGRAMMETRIC METHODS FROM AERIAL PHOTOGRAPH TAKEN IN MARCH 1969 BY ATLANTIC AERIAL SURVEY, INC. FOR TN STATE HIGHWAY DEPT. COORDINATE SYSTEM IS ASSUMED TO BE NAD27 TENNESSEE STATE PLANE ZONE (FIPS 4100), US FOOT.
2. ORIGINAL AND RELOCATED I-40 ALIGNMENTS ARE FROM AN ELECTRONIC SCAN OF "PROPOSED HORIZONTAL DRAINS, STATION 2003+00 TO STATION 2016+00, EAST BOUND LANE, 73001-3134-44", DATED SEPT. 1972 AND PROVIDED BY TDOT.
3. LAW ENGINEERING TESTING COMPANY, JUNE 25, 1969 "REPORT OF LANDSLIDE INVESTIGATION, INTERSTATE HIGHWAY PROJECT I-40-8 (40) 340, ROANE COUNTY, TENNESSEE", PROJECT NO. EC-236.
4. TDOT, 1972, I-40 ROANE COUNTY, "SLIDE E1 - EB1, STATION 2001+50 TO 2004+00, 73001-3134-44, I-40-8 (61) 340, ROANE COUNTY".
5. TDOT BORING LOGS, MARCH-APRIL, 1974, BUREAU OF HIGHWAYS, DIVISION OF SOILS AND GEOLOGICAL ENGINEERING.
6. TDOT BORING LOGS (WITH JENSEN DRILLING CO.), SEPT. 1974-JAN. 1975, BUREAU OF HIGHWAYS, DIVISION OF SOILS AND GEOLOGICAL ENGINEERING.
7. TDOT BORING LOGS, JUNE 2003, GEOTECHNICAL ENGINEERING, LOCATIONS ARE APPROXIMATE, BASED ON HANDHELD GPS JUNE 2009.
8. FARM SERVICE AGENCY 1:20,000 SCALE, BLACK AND WHITE, STEREOPAIR AERIAL PHOTOGRAPHS DATED OCTOBER 18, 1981 AND NOVEMBER 8, 1987.
9. TDOT HORIZONTAL DRAINS FROM "SOME OBSERVATIONS ON THE USE OF HORIZONTAL DRAINS IN THE CORRECTION AND PREVENTION OF LANDSLIDES", FIGURE 25, AUGUST 1977, BY DAVID L. ROYSTER, CHIEF, DIVISION OF SOILS AND GEOLOGICAL ENGINEERING.



FOR INTERNAL REVIEW
NOT FOR CONSTRUCTION

REV	DATE	DES	REVISION DESCRIPTION	CAD	CHK	REV
PROJECT TENNESSEE DEPARTMENT OF TRANSPORTATION I-40 LANDSLIDE SPECIAL DRAINAGE MEASURES						
TITLE SITE LAYOUT & EXISTING BORING LOCATIONS						
PROJECT No. 0738008901		FILE No.		SCALE AS SHOWN		REV.
DESIGN						
CADD	R/C	08/10				
CHECK	GE	08/10				
REVIEW	WRS	08/10				101




- In May of 2008, Golder Associates was hired to analyze and assess the history and provide recommendations for repairing the Major fill slide.

Two recommendations made in Phase I

- 1) Monitoring equipment- seven inclinometers were installed with piezometers located at possible aquifer depths, along with a weather station.
 - Current data shows that movement increases with rainfall.

2) Construction of a drainage system to alleviate some of the water pressure within the slope

R8 - Includes a proposal of 25 wells with regulated pumps with drain pipes linked to remove water from the slope without allowing it to re-infiltrate the surface, 4 piezometer standpipes, and 5 pads with between 4 and 9 horizontal drains at each pad.



PROPOS

ID
DW-1
DW-2
DW-3
DW-4
DW-5
DW-6
DW-7
DW-8
DW-9
DW-10
DW-11
DW-12
DW-13
DW-14
DW-15
DW-16
DW-17
DW-18
DW-19
DW-20
DW-21
DW-22
DW-23
DW-24
DW-25

PROPO

ID
MH-1
MH-2
MH-3
MH-4
MH-5
MH-6
MH-7
MH-8
MH-9
MH-10
MH-11
MH-12
MH-13
MH-14
MH-15
MH-16

LEGEND

	PRC
	PRC
	12' L
	PRC

REFERENCES
1. BASE MAP AND ACCESS HUTCHESON, INC.

DRAF



- As to date- the slope inclinometers were completed in early 2011 and have been monitored since.
- The rate of movement from march to april was 0.25 inches and slowed thru the summer weather. The peizometer data shows the fluctuation of the water table.
- The construction of the drainage system is to start in August of 2011.

From a review of the data and reports, remediation of the slope is going to be very expensive and unique to the situation.

Any Questions?